

1: T8217 2: T8217\_Cross branches



3: T8217\_Trunk base



4: T8217\_Parasitic vines\_01

## NL/2020/05 Photographic record (Monthly Monitoring Report for Preservation of Plant Species of Conservation Importance – June 2025)



5: T8217\_Parasitic vines\_02



6: T8231



7: T8231\_Borer holes\_01



9: T8231\_Dieback twigs

10: T8231\_Parasitic vines



11: T8231\_Old termite track

12: T8231\_Trunk base



13: Temporary protective fencing for U041, U042  $\label{eq:u043} \text{and U043}$ 

14: U041



15: U041\_Abnormal bark crack on trunk

16: U041\_Abnormal bark crack on trunk\_Close up



17: U041\_Crack on trunk

18: U041\_Crown



19: U041\_Wood damage at trunk union#1

20: U041\_Wood damage at trunk union#2



21: U041\_Wood damage at trunk union#3

22: U042



23: U042\_Wound on trunk base

24: U043



25: U043\_Crack on trunk

26: U043\_Crown



27: U043\_Wound on trunk#1

28: U043\_Wound on trunk#2



29: U043\_Wound on trunk#3

30: Temporary protective fencing for U041, U042  $and \ U043$ 



31: Application of pesticide for U041

32: Adjust protection pad for U041

NL/2020/05 Photographic record (Monthly Monitoring Report for Preservation of Plant Species of Conservation Importance – June 2025)



33: Crown cleaning for T8217 and neaby Trees

## Tree Schedule for Survey of Plant Species of Conservation Importance

Tree No.	Species			Measurements			Amenity Value (High(H) /	Tree Condition (Good(G) / Average(A) / Poor(P))			Recommendation		
	Scientific Name	Chinese Name	Conservation Status	Height (m)	DBH (mm)	Crown Spread (m)	Medium (M) / Low(L)	Form	Health	Structure	(Retain / Transplant / Remove)	Findings	Remark
T8217	Canthium dicoccum	魚骨木	IUCN:VU	9	220	6	L	P	A	P	Retain	Parasitic vines Cassytha filiformis was observed	There is no proper and safe assess towards T8231 & T8217, thus, plastics barriers were installed in lieu of 2m high barrier. Removal of Parasitic vines Cassytha filiformis and crown cleaning was performed on 10 June 2025.
T8231	Canthium dicoccum	魚骨木	IUCN:VU	7	190	6	L	P	A	P	Retain	Old termite track with borer hole was observed on trunk in June 2025, no live termite activity was found during time of inspection. Parasitic vines Cassytha filiformis along with dead twigs and minor signs of dieback were observed	There is no proper and safe assess towards T8231 & T8217, thus, plastics barriers were installed in lieu of 2m high barrier. Epiconmic branch failure was found on 03 May 2024. Staking to provide extra support and pruning of jagged wound to provide a clean cut was conducted on 16 May 2024. Application of insecticide and fungicide on wound was conducted on 3 June 2025, The Staking was in normal condition during the time of inspection. Old termite track with borer hole was observed on trunk in June 2025, no live termite activity was found during time of inspection. Removal of Parasitic vines Cassytha filiformis and crown cleaning was performed on 10 June 2025.
U041	Aquilaria sinensis	土沉香	RPPHK; Cap.586; IUCN:VU	10	318	4	М	A	P	P	Retain	No obvious old termite track was found, damage of wood tissue was observed. Peeling off of bark and sign of split of internal wood tissue was observed. Trunk wound signficantly decayed. High trunk failure risk.	Located closed to cut slope. The crack on trunk was found slightly larger since late March 2024. Peeling off of bark and split of internal wood tissue was observed in July 2024. Abnormal bark crack was found in December 2024. Additional guying for tree no. 1041 has been installed as an enhanced stabilization measure alongside the bamboo staking in May 2025. Adjustment of guying and application of insecticide and fungicide was conducted on 10 June 2025 and 3 June 2025 respectively.
U042	Gmelina chinensis	石梓	RРРНК	6	150	2	М	A	P	A	Retain	Large wound near trunk base with wound wood development. Trunk wound is decaying.	Located closed to cut slope. Application of insecticide was conducted on 3 June 2025.
U043	Aquilaria sinensis	土沉香	RPPHK; Cap.586; IUCN:VU	9	310	4	M	A	Р	P	Retain	Crack on trunk base. Trunk wound significantly decayed. High trunk failure risk.	Located closed to cut slope and fenced off by 2m high barrier. Application of insecticide and fungicide was conducted on 3 June 2025.