

<p>A8 – Overall view</p>	<p>A8 – Foliage density was similar comparing to last inspection photos. While leaves were greener</p>
 <p>A photograph showing a young tree (A8) supported by a tripod of bamboo poles. The tree is wrapped in black mesh and has a burlap cover over its top. It is situated in a construction area with white and red barriers and other trees in the background. A date stamp '11 12 2023' is visible in the bottom right corner.</p>	 <p>A close-up photograph of the foliage of tree A8, showing dense green leaves against a cloudy sky. A date stamp '11 12 2023' is visible in the bottom right corner.</p>
<p>A8 – Pruning wound previously damaged by typhoon KOINU (Oct 2023)</p>	<p>A8 – trunk condition.</p>
 <p>A close-up photograph of the trunk of tree A8, showing a pruning wound. The trunk is dark and textured, with green leaves visible in the upper part of the frame. A date stamp '11 12 2023' is visible in the bottom right corner.</p>	 <p>A photograph of tree A8 from a different angle, showing the tripod support and the burlap cover. The tree is in a construction area with barriers. A date stamp '11 12 2023' is visible in the bottom right corner.</p>

<p>A12 - Overall View</p>	<p>A12 – Foliage density is low since its collapse during Typhoon KOINU</p>
 <p>A photograph showing the overall view of tree A12. The tree is supported by a bamboo tripod structure. Its base is wrapped in black mesh and burlap. The tree is situated behind a white and red plastic barrier. The date '11 12 2023' is printed in yellow at the bottom right.</p>	 <p>A close-up photograph of tree A12, showing its sparse foliage and the bamboo support structure. The tree's trunk is visible, and the date '11 12 2023' is printed in yellow at the bottom right.</p>
<p>A12 – Codominant branch with included bark</p>	<p>A12 – trunk and root condition</p>
 <p>A photograph focusing on a codominant branch of tree A12, showing a clear inclusion of bark. The date '11 12 2023' is printed in yellow at the bottom right.</p>	 <p>A photograph showing the trunk and root condition of tree A12. The tree is supported by a bamboo tripod structure. The base is wrapped in black mesh and burlap. The date '11 12 2023' is printed in yellow at the bottom right.</p>

Trunk protection wrapping was adjusted away from the trunks on 13 Nov 2023. Slightly fertilizing was performed.



Additional shading net was installed



The semiautomatic irrigation was checked and is in order. Current watering frequency is three times per week



CCTV and fencing are in order



Tree Schedule for Survey of Plant Species of Conservation Importance

No.	Species		Conservation Status	Measurements			Tree Condition (Good(G) / Average(A) / Poor(P))			Recommendation (Retain / Transplant / Remove)	Findings	Remark
	Scientific Name	Chinese name		DBH (mm)	Height (m)	Crown (m)	Form	Health	Structure			
A8 (T8996)	<i>Aquilaria sinensis</i>	土沉香	RPPHK; Cap.586; IUCN:VU	110	5	4	P	A	P	Transplant	Foliage density is not yet improved in current inspection. The leaves are now greener.	Originally located at Site 1. Trunk wounds were observed before transplant operation. Shallow root. Sudden defoliation happened on May 2023 but recovered on Aug 2023. It was translocated to the temporary holding nursery on 29 Sep 2023. A branch (5cm) was broken and foliage density decreased due to typhoon on Oct 2023.
A12 (T3537)	<i>Aquilaria sinensis</i>	土沉香	RPPHK; Cap.586; IUCN:VU	185	8	3	A	P	A	Transplant	Foliage density is not yet improved in current inspection.	Originally located at Site 5. Trunk wounds were observed before transplant operation. Shallow root. Original root ball was full of stones which were removed partially during the translocation. It was translocated to the temporary holding nursery on 29 Sep 2023. It collapsed during typhoon dated Oct 2023 resulted in largely reduction in foliage density.

*Note:

DBH refers to Trunk Diameter at Breast Height

The Tree preservation work commenced in Jul 2022

RPPHK - Species included in AFCD publication "Rare and Precious Plants of Hong Kong (2003)"

Cap.586 – Native plants listed in Protection of Endangered Species of Animals and Plants Ordinance, Cap. 586.

IUCN:VU – "Vulnerable" under IUCN Red List of Threatened Species