

<p>A8 – Overall view</p>	<p>A8 – Foliage density was similar comparing to last inspection photos. While leaves were greener</p>
 <p>A photograph showing a young tree (A8) at a construction site. The tree is supported by a black mesh cage and wooden stakes. In the background, there are white and red safety barriers and other trees. The date '10 01 2024' is printed in yellow at the bottom right.</p>	 <p>A close-up photograph of the foliage of tree A8, showing green leaves against a clear blue sky. The date '10 01 2024' is printed in yellow at the bottom right.</p>
<p>A8 – Pruning wound previously damaged by typhoon KOINU (Oct 2023)</p>	<p>A8 – trunk condition.</p>
 <p>A close-up photograph of the trunk of tree A8, showing a pruning wound. The date '10 01 2024' is printed in yellow at the bottom right.</p>	 <p>A photograph showing the trunk of tree A8 supported by a black mesh cage and wooden stakes. The date '10 01 2024' is printed in yellow at the bottom right.</p>

<p>A12 - Overall View</p>	<p>A12 – Foliage density is low since its collapse during Typhoon KOINU</p>
 <p>A photograph showing a young tree with a sparse canopy supported by a wooden tripod structure. The base of the tree is wrapped in black mesh. In the background, there are white and red plastic barriers and a clear blue sky. A yellow date stamp '10 01 2024' is visible in the bottom right corner.</p>	 <p>A close-up photograph of the tree's trunk and branches, highlighting the sparse, yellowish-green foliage. The trunk is light-colored and shows some texture. The background is a clear blue sky. A yellow date stamp '10 01 2024' is visible in the bottom right corner.</p>
<p>A12 – Codominant branch with included bark</p>	<p>A12 – trunk and root condition</p>
 <p>A close-up photograph of a codominant branch on the tree, showing a clear inclusion of bark between the branch and the main trunk. The branch is thin and has sparse foliage. The background is a clear blue sky. A yellow date stamp '10 01 2024' is visible in the bottom right corner.</p>	 <p>A close-up photograph of the tree's trunk and root area, showing the support structure and the black mesh wrapping. The trunk is light-colored and shows some texture. The background is a clear blue sky. A yellow date stamp '10 01 2024' is visible in the bottom right corner.</p>

Tung Chung New Town Extension – Site Formation and Infrastructure Works at Tung Chung Valley, Phase 1

Manual watering was carried out for A8 during the reporting period. The watering frequency is three time per week.



Manual watering was carried out for A12 during the reporting period. The watering frequency is three time per week.




The semiautomatic irrigation was checked and is in order. The watering frequency is three times per week



CCTV and fencing are in order



<p>Apply diluted organic liquid fertilizer</p>  <p>10 01 2024</p>	<p>Apply diluted organic liquid fertilizer</p>  <p>10 01 2024</p>
<p>Apply quick release fertilizer in small dosage – A8</p>  <p>19 01 2024</p>	<p>Apply quick release fertilizer in small dosage - A12</p>  <p>19 01 2024</p>



Tree Schedule for Survey of Plant Species of Conservation Importance

No.	Species		Conservation Status	Measurements			Tree Condition (Good(G) / Average(A) / Poor(P))			Recommendation (Retain / Transplant / Remove)	Findings	Remark
	Scientific Name	Chinese name		DBH (mm)	Height (m)	Crown (m)	Form	Health	Structure			
A8 (T8996)	<i>Aquilaria sinensis</i>	土沉香	RPPHK; Cap.586; IUCN:VU	110	5	4	P	A	P	Transplant	Foliage density is not yet improved in current inspection. The leaves are now greener.	Originally located at Site 1. Trunk wounds were observed before transplant operation. Shallow root. Sudden defoliation happened in May 2023 but recovered in Aug 2023. It was translocated to the temporary holding nursery on 29 Sep 2023. A branch (5cm) was broken and foliage density decreased due to typhoon in Oct 2023.
A12 (T3537)	<i>Aquilaria sinensis</i>	土沉香	RPPHK; Cap.586; IUCN:VU	185	8	3	A	P	A	Transplant	Foliage density is not yet improved in current inspection.	Originally located at Site 5. Trunk wounds were observed before transplant operation. Shallow root. Original root ball was full of stones which were removed partially during the translocation. It was translocated to the temporary holding nursery on 29 Sep 2023. It collapsed during typhoon dated Oct 2023 resulted in largely reduction in foliage density.

*Note:

DBH refers to Trunk Diameter at Breast Height

The Tree preservation work commenced in Jul 2022

RPPHK - Species included in AFCD publication "Rare and Precious Plants of Hong Kong (2003)"

Cap.586 – Native plants listed in Protection of Endangered Species of Animals and Plants Ordinance, Cap. 586.

IUCN:VU – "Vulnerable" under IUCN Red List of Threatened Species