




<p>A8 – Overall view</p>  A photograph showing the overall view of tree A8. The tree is a young sapling with green leaves, supported by a wooden tripod frame. It is situated in a grassy area with a black mesh cage around its base. In the background, there are white and red plastic barriers and other trees. A yellow date stamp "07 02 2025" is visible in the bottom right corner. <p>07 02 2025</p>	<p>A8 – Crown condition.</p>  A close-up photograph of the crown of tree A8, showing its green foliage against a cloudy sky. A yellow date stamp "07 02 2025" is visible in the bottom right corner. <p>07 02 2025</p>
<p>A8 – Pruning wound previously damaged by typhoon KOINU (Oct 2023)</p>  A close-up photograph of a pruning wound on the trunk of tree A8. The wound is a vertical cut in the bark, showing a lighter-colored interior. A yellow date stamp "07 02 2025" is visible in the bottom right corner. <p>07 02 2025</p>	<p>A8 – Trunk and root condition.</p>  A photograph showing the trunk and root area of tree A8. The tree is supported by a wooden tripod frame, and a black mesh cage is around its base. The ground is grassy with some fallen leaves. A yellow date stamp "07 02 2025" is visible in the bottom right corner. <p>07 02 2025</p>

<p>A8 – Decaying wound at trunk base (size: ~180mm x170mm)</p> 	<p>A8 – Decaying wound on trunk</p> 
---	---

A12 - Overall View	A12 - Dieback observed. Dead branches were removed on 07/12/2024
 A photograph showing the overall view of tree A12. The tree is a young, slender specimen with a thin trunk and sparse green foliage. It is supported by a wooden tripod structure. The base of the tree is surrounded by a black mesh cage. In the background, there are white and red plastic barriers and a black tarp. The sky is overcast. A yellow timestamp "07 02 2025" is visible in the bottom right corner. <p>07 02 2025</p>	 A close-up photograph of the upper part of tree A12, showing its canopy. The branches are mostly bare, with some green leaves visible. The trunk is light brown and shows signs of dieback. The background is a cloudy sky. A yellow timestamp "07 02 2025" is visible in the bottom right corner. <p>07 02 2025</p>
A12 - Foliage density is still low.	A12 – Trunk and root condition
 A close-up photograph of the upper part of tree A12, showing its canopy. The branches are mostly bare, with some green leaves visible. The trunk is light brown and shows signs of dieback. The background is a cloudy sky. A yellow timestamp "07 02 2025" is visible in the bottom right corner. <p>07 02 2025</p>	 A photograph showing the trunk and root condition of tree A12. The tree is supported by a wooden tripod structure. The base of the tree is surrounded by a black mesh cage. In the background, there are white and red plastic barriers and a black tarp. The sky is overcast. A yellow timestamp "07 02 2025" is visible in the bottom right corner. <p>07 02 2025</p>

<p>A12 –Wound at trunk base</p>  <p>07 02 2025</p>	<p>A12 – Decaying wound on trunk</p>  <p>07 02 2025</p>
<p>Adjustment of tree supportive system was carried out on 3 Feb 2025</p>  <p>03 02 2025</p>	<p>Grass cutting of surrounding soil area on 3 Feb 2025</p>  <p>03 02 2025</p>

Manual watering was carried out for A8 during the reporting period. The watering frequency is one to two times per week.




Manual watering was carried out for A12 during the reporting period. The watering frequency is one to two times per week.



CCTV and fencing are in order.



Weeding was done on 03/02/2025



<p>CCTV Screen captures at day-time</p>  <p>2025年03月03日 星期一 11:46:56</p> <p>Camera 01</p>	<p>CCTV Screen captures at day-time</p>  <p>2025年03月03日 星期一 11:45:17</p>
<p>CCTV Screen captures at night-time</p>  <p>2025年03月04日 星期二 18:49:15</p> <p>Camera 01</p>	<p>CCTV Screen captures at night-time</p>  <p>2025年02月04日 星期二 19:03:28</p>

Tree Schedule for Survey of Plant Species of Conservation Importance

No.	Species		Conservation Status	Measurements			Tree Condition (Good(G) / Average(A) / Poor(P))			Recommendation (Retain / Transplant / Remove)	Findings	Remark
	Scientific Name	Chinese name		DBH (mm)	Height (m)	Crown (m)	Form	Health	Structure			
A8 (T8996)	<i>Aquilaria sinensis</i>	土沉香	RPPHK; Cap.586; IUCN:VU	110	5	4	P	A	P	Transplant	No specific observation.	Originally located at Site 1. Trunk wounds were observed before transplant operation. Shallow root. Sudden defoliation happened in May 2023 but recovered in Aug 2023. It was translocated to the temporary holding nursery on 29 Sep 2023. A branch (5cm) was broken and foliage density decreased due to typhoon in Oct 2023.
A12 (T3537)	<i>Aquilaria sinensis</i>	土沉香	RPPHK; Cap.586; IUCN:VU	185	8	3	P	P	A	Transplant	The foliage density is low.	Originally located at Site 5. Trunk wounds were observed before transplant operation. Shallow root. Original root ball was full of stones which were removed partially during the translocation. It was translocated to the temporary holding nursery on 29 Sep 2023. It collapsed during typhoon dated Oct 2023 resulted in largely reduction in foliage density. It was slightly lean after a typhoon event dated 13-14 Nov 2024 and reinstated.

*Note:

DBH refers to Trunk Diameter at Breast Height

The Tree preservation work commenced in Jul 2022

RPPHK - Species included in AFCD publication "Rare and Precious Plants of Hong Kong (2003)"

Cap.586 – Native plants listed in Protection of Endangered Species of Animals and Plants Ordinance, Cap. 586.