
A11 – Overall view	A11 – Crown condition.
	
A11 – Shoots are epicormic generated from cut trunk which is decaying severely	Pest control done on 21/09/2026
	

CEDD Contract No. NL/2020/06

Tung Chung New Town Extension – Site Formation and Infrastructure Works at Tung Chung Valley, Phase 1

CCTV Screen



Tree Schedule for Survey of Plant Species of Conservation Importance

No.	Species		Conservation Status	Measurements			Tree Condition (Good(G) / Average(A) / Poor(P))			Recommendation (Retain / Transplant / Remove)	Findings	Remark
	Scientific Name	Chinese name		DBH (mm)	Height (m)	Crown (m)	Form	Health	Structure			
A9 (T7628)	*Aquilaria sinensis*	土沉香	RPPHK; Cap.586; IUCN:VU	-	-	-	-	-	-	-	-	Removed due to illegal felling on Aug 2023 (reported to police on 21 Aug 2023)
A10 (T7538)	*Aquilaria sinensis*	土沉香	RPPHK; Cap.586; IUCN:VU	-	-	-	-	-	-	-	-	Removed due to illegal felling on Aug 2023 (reported to police on 21 Aug 2023)
A11 (T7521)	*Aquilaria sinensis*	土沉香	RPPHK; Cap.586; IUCN:VU	190	3.5	1	P	A	P	Retain	Insect infestation is low.	Root-plate movement (mentioned in previous monitoring report). Topped tree due to illegal felling on Aug 2023 (reported to police on 21 Aug 2023). Large decaying trunk wound. Foliage density reduced after inclement weather events on Aug and Sep 2025. Unknown physical damage is observed resulting in the breaking of some epicormic shoots on Nov 2025 (Cleaned).

*Note:

DBH refers to Trunk Diameter at Breast Height


The Tree preservation work commenced in Jul 2022

RPPHK - Species included in AFCD publication "Rare and Precious Plants of Hong Kong (2003)"



Cap.586 – Native plants listed in Protection of Endangered Species of Animals and Plants Ordinance, Cap. 586.

IUCN:VU – "Vulnerable" under IUCN Red List of Threatened Species


A8 – Overall view	A8 – Pruning wound previously damaged by typhoon KOINU (Oct 2023)
	
A8 – Decaying wound on trunk	A8 – Trunk and root condition.
	

A8 – Decaying wound at trunk base (size: ~180mm x170mm)	A8 –Leaves chlorosis and thin.
	
A8 – Foliage density reduced after fruiting, hot weather and Typhoon on July 2026	A8 – dieback
	

A12 - Overall View	A12 – Crown condition
	
A12 - Foliage density reduced after repeatedly heavy rains	A12 – Trunk and root condition
	

A12 –Wound at trunk base	A12 – Epicormics on trunk. Decaying wound on Trnnk.
	
Fencing is in order during inspection	Grass cutting and weeding was conducted on 1 September 2026.
	

Grass cutting and weeding was conducted on 22 September 2026.	Application of mineral oil (as antitranspirant) was conducted on 22 September 2026.
	
Manual watering was carried out for A8 during the reporting period. The watering frequency is one to two times per week.	Manual watering was carried out for A12 during the reporting period. The watering frequency is one to two times per week.
	

CCTV Screen captures at day-time	CCTV Screen captures at day-time
	
CCTV Screen captures at night-time	CCTV Screen captures at night-time
	

Tree Schedule for Survey of Plant Species of Conservation Importance

No.	Species		Conservation Status	Measurements			Tree Condition (Good(G) / Average(A) / Poor(P))			Recommendation (Retain / Transplant / Remove)	Findings	Remark
	Scientific Name	Chinese name		DBH (mm)	Height (m)	Crown (m)	Form	Health	Structure			
A8 (T8996)	*Aquilaria sinensis*	土沉香	RPPHK; Cap.586; IUCN:VU	110	5	4	P	P	P	Transplant	No obvious wound wood production. Very low foliage density. Dieback Severity of the insect feeding was low.	Trunk wounds were observed before transplant operation. Shallow root. Sudden defoliation happened in May 2023 but recovered in Aug 2023. It was translocated to the temporary holding nursery on 29 Sep 2023. A branch (5cm) was broken due to typhoon in Oct 2023. Decaying wounds and exposed dead woods on trunk. The foliage density is low especially after inclement weather events on Aug/Sep 2025. The tree recovered partially on Spring 2026. However recent heavy raining, hot weather on June and July resulted in the reduction in foliage density. Foliage density becomes very low after tropical cyclone warning signal No. 9 event on July 2026.
A12 (T3537)	*Aquilaria sinensis*	土沉香	RPPHK; Cap.586; IUCN:VU	185	8	3	P	P	A	Transplant	No obvious wound wood production. Severity of the insect feeding was low.	Trunk wounds were observed before transplant operation. Shallow root. Original root ball was full of stones which were removed partially during the translocation. It was translocated to the temporary holding nursery on 29 Sep 2023. It collapsed during typhoon dated Oct 2023 resulted in largely reduction in foliage density. It was slightly lean after a typhoon event dated 13-14 Nov 2024 and reinstated. Decaying wounds and exposed dead woods on trunk. The foliage density is low especially after inclement weather events on Aug/Sep 2025. The tree recovered partially on Spring 2026. However recent heavy raining, hot weather on June and July resulted in the reduction in foliage density.

*Note:

DBH refers to Trunk Diameter at Breast Height

The Tree preservation work commenced in Jul 2022

RPPHK - Species included in AFCD publication "Rare and Precious Plants of Hong Kong (2003)"

Cap.586 – Native plants listed in Protection of Endangered Species of Animals and Plants Ordinance, Cap. 586.